

APPROVED: 10th June 2026

Description:

Reviewing risk involved to the public when using the benches provided in public areas by the Community Council.

The benches provided are of substantial construction and manufactured for use as street furniture in public environments.

Previous incidents

There have been **NO** reported incidents since the benches were installed

Hazard information	Control measure(s) currently in place	Potential harm (most common if current control fails)	Risk Rating (1 – 5 Low to High)	Control Measures
Vandalism	Regular visual inspection	Cuts and bruising, items being unsafe to use, falls, injury to limbs, head or back	1	Regular visual inspections. DO NOT USE signage to be placed on any damaged item posing a risk to health or if severe damage item will be removed.
General aging	Regular visual inspection	None perceived	1	Regular visual inspections.
Lack of maintenance	Regular visual inspection	Cuts and bruising, items being unsafe to use, falls, injury to limbs, head or back	1	Regular visual inspections. DO NOT USE signage to be placed on any damaged item posing a risk to health or if unsafe to use the item will be removed.

Does additional risk arise in an emergency situation? **NO** It is not assessed that there is additional emergency risk involved.

Inspections Frequency : Visual inspection for all street furniture at monthly intervals.

Street Furniture belonging to Llangelynnin Community Council : 3 Bus Shelters/3 Noticeboards/14 Benches/4 Defibrillators & Cabinets